

TA-1000

## Bar lathe



► CNC bar lathe, with automatic loading and unloading. Outer camshaft turning, capping and grooving.

**CUSTOMIZED SPECIAL MACHINES**



## DESCRIPTION

- Adapted machine for integration with other stations or to be used individually, with or without post-processing.
- Two toolholders.
- Five CNC axes.
- Two supporting steady rests on the CNC cart.
- CNC-positioned tailstock.
- Sliding plate and spot with sliders for complete machining of the bar.
- Loading and unloading time: 7 sec.